

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Environ., Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	WELL API NO. 30-025-09387
2. Name of Operator Energen Resources Corporation	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator 3300 N. "A" St., Bldg 4, Ste. 100, Midland, TX 79705	6. State Oil & Gas Lease No. 23267
4. Well Location Unit Letter <u>K</u> : <u>1650</u> feet from the <u>South</u> line and <u>2310</u> feet from the <u>West</u> line Section <u>23</u> Township <u>23S</u> Range <u>36E</u> NMPM County <u>Lea</u>	7. Lease Name or Unit Agreement Name: Langlie Lynn Queen Unit
8. Well No. 4	
9. Pool name or Wildcat Langlie Mattix 7 RVR/Queen/GB	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

02/22-23/00: MIRUPU. pulled production equipment. Cleaned out fill to new PBTD of 3,685'. (could not bail any deeper).

02/24/00: Re-perforated the 7 RVR/ Queen @ 3,440'-78'. (total of 152 holes). Old perms @ 3,440'-3,526' & 3,542'-3,628'. Acidized perms w/ 3M gals 15% HCL acid.

02/29/00: RIH w/ rods & 2 3/8" tubing. Tubing landed @ 3,660'. RDPU & RWTP.

03/05/00: Retest: 3 B0/ 27 BW.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Menoud TITLE Production Tech. DATE 03/21/00

Type or print name Denise Menoud

Telephone No. (915)687-2074

(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any: