	O OIL CONSER LLANEOUS RE District Office	PORTS ON	WELLS	5	Form C- (Revised CCC (196) 3 : 32	3-55)
COMPANY Gulf	011 Corporation		Hobbs,	New Mexi	.00	
	(Addr	ess)				
LEASE Alice Paddock	WELL NO	3 UNIT	P S	<u>1</u> T	<b>22-</b> S	R <b>37-E</b>
DATE WORK PERFORMED	7-11-56 11-3	-56 POOL	Tubb			
This is a Report of: (Check	appropriate bl	.ock)	Result	s of Tes	t of Casin	g Shut-off
Beginning Drilling	Operations	X	Reme	dial Wor	k	
Plugging		X	Other	Dually c	cmpleted	

------

Detailed account of work done, nature and quantity of materials used and results obtained.

SEE ATTACHES SHEET

FILL IN BELOW FOR REMEDIAL WORK	REPORTS ONLY			
Original Well Data:				
DF Elev. 3358 TD 7064 PBD 6350	Prod. Int. 6120-63501 Compl Date 8-26-16			
Tbng. Dia 2-3/8" Tbng Depth 6262! O	il String Dia 7" Oil String Depth 6953'			
Perf Interval (s) 6150-6190' 6210-62	01			
Open Hole Interval Produc	ing Formation (s) <b>Tubb</b>			
RESULTS OF WORKOVER:	BEFORE AFTER			
Date of Test				
Oil Production, bbls. per day				
Gas Production, Mcf per day				
Water Production, bbls. per day				
Gas-Oil Ratio, cu. ft. per bbl.				
Gas Well Potential, Mcf per day				
Witnessed by C. C. Brown	Gulf Oil Corporation			
	(Company)			
OIL CONSERVATION COMMISSION	I hereby certify that the information given above is true and complete to the best of			
Name El. Fricker	my knowledge. Name 37 Jul 5-			
Title Engineer District )	Position Area Supt. of Prod.			
Date NOV 9 1956	Company Gulf Vil Corporation			

Dually completed as Blinebry and Tubb as follows: (01) (Gas)

- Pulled tubing. "an steel line measurement to 6350". "et Baker Model D production packer on wire line at 6100". Kan 201 joints 2-3/8" tubing with GOT circulating valve in open position at 6166", seal nipple at 6134" and GOT circulating valve in closed position at 6067". Swabbed and well kicked off.
- Closed circulating valve at 6166'. Unlatched from packer, pulled tubing and seal nipple. Perforated 7" casing from 5545-5600', 5634-5690' and 5735-5760' with 2, 1/2" jet holes per foot.
- 3. Ran 2-3/8" tubing with bridge plug at 5771' and parent packer at 5724'. Swabbed dry. Treated formation thru perforations in 7" casing from 5735-5760' with 2000 gallens 155 HE acid. Injection rate 23 bbls per minute. Swabbed dry. Reset bridge plug at 5700' and parent packer. at 5625'. Swabbed dry. Treated formation thru perforations in 7" casing from 5635-5690' with 5000 gallens 155 HE acid. Injection rate 1.8 bbls per minute. Swabbed dry. Reset bridge plug from 5700' to 5610' and parent packer at 5535'. Swabbed dry. Treated formation thru perforations in \$" casing from 5545-5600' with 5000 gallens 15% HE acid. Injection rate 2 bbls per minute. Swabbed dry.
- 4. Tested casing with 900%, OE. Fulled 2-3/8" tubing, bridge plug and parent packer. Han 3-1/2" tubing with 7" packer at 3442'. Treated formation thru perforations in 7" casing from 5545-5760' with 18,000 gallons refined oil with 1# sand per gallon. Injection rate 14 bbls per minute. Pulled tubing and packer.
- 5. Ran 2-3/8" tubing with parent pasker at 5476". Swabbed and well kicked off. Pulled tubing and parent pasker. Ran 2-3/8" tubing and seal nipple set in packer at 6100". Swabbed and well kicked off.
- 6. Closed circulating valve in Blinebry Zone at 6063'. Blinebry Zone temporarily closed in. Well now producing from Tubb Gas Zone.