

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S | |
| LAND OFFICE | |
| OPER OR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| <input checked="" type="checkbox"/> & <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- | 5a. Indicate Type of Lease Date <input type="checkbox"/> Fee <input checked="" type="checkbox"/> |
| 1. Name of Operator Cities Service Oil Company | 5. State Oil & Gas Lease No. |
| 2. Address of Operator Box 1919 - Midland, Texas 79701 | 6. Name of Lease Name Brunson B |
| 3. Location of Well UNIT LETTER M 4620 FEET FROM THE North LINE AND 4620 FEET FROM THE East LINE, SECTION 3 TOWNSHIP 22S RANGE 37E NMPM. | 7. Unit Agreement Name 8. Well No. 3 |
| 10. Field, Pool, or Wildcat Drinkard Oil & Tubb Gas | 12. County Lea |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3433' DF | |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

| | |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> |

SUBSEQUENT REPORT OF:

| | |
|--|--|
| REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOBS <input type="checkbox"/> | OTHER <input checked="" type="checkbox"/> Relocating cellar valves above the ground and filling the cellar with sand. |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated dates of completion, if any proposed work) SEE RULE 1103.

The valves located in the cellar were removed, a 2" riser installed and the valves have been relocated above the ground. The valves have been marked as to which zone they service and the cellar has been filled with sand.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Elmer Stutz TITLE Region Petroleum Engineer

Jan. 30, 1976

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: