

Place Hobbs, New Mexico
Date January 2, 1947

Glenn Staley
Proration Office
Hobbs, New Mexico.

Designate UNIT well is located in
E

D	C	B	A
E	F	G	H
L	K	J	I
M	N	O	P

Recompletion
NOTICE OF COMPLETION OF: (Lease) Ev. Owen A Well No. 1
1980 feet from N line: 660 feet from W line;
Section 3 Township 22 Range 37.

DATE STARTED 10-24-46
DATE COMPLETED 12-31-46
ELEVATION 3433
TOTAL DEPTH S.L. 7356 FB to 6615
CABLE TOOLS _____ ROTARY TOOLS X

CASING RECORD

SIZE	<u>5" OD</u>	DEPTH	<u>6658</u>	SAX CEMENT	<u>180</u>
SIZE		DEPTH		SAX CEMENT	
SIZE		DEPTH		SAX CEMENT	

TUBING RECORD

SIZE 2" DEPTH 6600

ACID RECORD

NO. GALS 500
NO. GALS 1000
NO. GALS 3000

SHOT RECORD

NO. QTS. _____
NO. QTS. _____
NO. QTS. _____

FORMATION TOPS

Top Gorieta 5060
Anhydrite _____
Top Salt _____
Base Salt _____
Red Sand _____
Brown Lime _____
White Lime _____
Oil or Gas Pay _____
Water _____

Initial Production Test _____ Pumping _____ Flowing _____
Test After Acid or Shot Flowed 56 BO / 10 bbls. acid water in 2-1/2 hrs. thru
open 2".
Initial GAS VOLUME _____

SCHEDULE NO. _____ DATE _____

PIPE LINE TAKING OIL Shell Pipe Line Company

REMARKS This is an old well in COMPANY Stanolind Oil and Gas Company
Penrose-Skelly Pool drilled deeper and
recompleted in the Drizard Pool. SIGNED BY: Xeph L. Neunduckson

cc: Oil Conservation Commission

1. The first part of the document discusses the importance of maintaining accurate records of all transactions and activities. It emphasizes that proper record-keeping is essential for ensuring transparency and accountability in the organization's operations.

2. The second part of the document outlines the various methods and tools used to collect and analyze data. It highlights the need for consistent data collection procedures and the use of appropriate statistical techniques to interpret the results.

3. The third part of the document describes the process of identifying and addressing potential risks and challenges. It stresses the importance of proactive risk management and the need to develop effective mitigation strategies.

4. The fourth part of the document discusses the role of communication and collaboration in achieving the organization's goals. It emphasizes the need for clear communication channels and effective teamwork to ensure that all stakeholders are aligned and working towards the same objectives.

5. The fifth part of the document provides a summary of the key findings and conclusions of the study. It highlights the main insights gained from the data analysis and the implications for the organization's future actions.

6. The sixth part of the document includes a list of references and a bibliography, providing sources for the information and data used in the study.

7. The seventh part of the document contains a list of appendices, which include additional data, charts, and supporting documents that are not included in the main body of the report.

8. The eighth part of the document is a concluding statement, summarizing the overall purpose and findings of the study and expressing the hope that the information provided will be useful to the organization.