STATE OF NEW MEXICO	AIT		
ENERGY AND MANAGERALS DEPARTME	OIL CONSERVAT	ION DIVISION	Form C-103
DISTRIBUTION	P. O. BOX 2	2088	Revised 10-1-78
SANTA PE	SANTA FE, NEW M	IEXICO 87501	
FILE			Sa. Indicate Type of Leuse
U.S.G.S.			State Fee V
LAND OFFICE			5. State Oll & Gas Lease No.
OPERATOR			
SUNDR	Y NOTICES AND REPORTS ON WI	ELLS N TO A DIFFERENT RESERVOIR. ROPOSALS.)	7. Unit Agreement Name
	07HER-		
and the second			8. Farm or Lease Name
2. Name of Operator ARCO Oil	and Gas Company		R.L. Brunson
Division of Atlantic Richfield Co.			9. Well No.
3. Address of Operator			
P.O. Box 1710, Hobbs, New Mexico 88240			10. Field and Pool, or Wildcat
4. Location of Well			
UNIT LETTERO,554 FEET FROM THESOUTH_LINE AND2086 FEET FROM			
THE <u>East</u> line, section <u>4</u> township <u>228</u> Range <u>37E</u> HMPM.			- VIIIIIIIIIIIIIIIIIIIII
	15. Elevation (Show whether DI 3425 'G		Lea
16. Chack	Appropriate Box To Indicate National	ture of Notice, Report or C	Ither Data
	NTENTION TO:	SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK		REMEDIAL WORK	ALTERING CASING
PULL OR ALTER CABING	CHANGE PLANS	CASING TEST AND CEMENT JOB [] OTHER pipe casing t	o top of ground
OTHER		_	
	perations (Clearly state all pertinent detail	ls, and give pertinent dates, includ	ing estimated date of starting any propose

work) SEE RULE 1103.

Dug cellar out to 13 3/8" casing head. Piped 13 3/8" to top of ground w/2" pipe, installed 2" ball valve and stenciled SUR on side of valve. Piped 8 5/8" casing to top of ground, installed 2" ball valve and stenciled INT on side of valve. Work inspected by Mr. Ron Castleberry w/NMOCD on 4/20/83.

18. I hereby certify that the information above is true and complet	le to the best of my knowledge and belief.	
L. Ahackelfant	Engrg. Tech. Spec.	4/22/83
	OIL & GAS INSPECTOR	APP 25 1003
	T)TLC	*** <b>**********************************</b>
CONDITIONS OF APPROVAL, IF ANY		

