Form 9-331 (May 1963)	UNIT O STATES DEPARTMEN JF THE INTE GEOLOGICAL SURVEY			
(The wet was this for	AY NOTICES AND REPORTS in for proposals to drill or to deepen or pl se "APPLICATION FOR PERMIT—" for suc	ug back to a different reservoir.		
1. OIL GAS WELL WELL	7. UNIT AGREEMENT NAME South Penrose Skelly Unit 8. FARM OR LEASE NAME			
2. NAME OF OPERATOR Gulf Oil Corporation 3. ADDRESS OF OPERATOR Box 670 Hobbs, N.M. 88240 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FEL, Section 7, 22S, 37E 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) oll (1, GT)			9. WELL NO. 153 10. FIELD AND POOL, OR WILDCAT Penrose Skelly 11. SBC., T., R., M., OR BLK. AND SURVEY OR ABEA Sec. 7,22S, 37E 12. COUNTY OR PARISH Lea New Mexico	
16.	Check Appropriate Box To Indicat	3446 <sup>+</sup> GL te Nature of Notice, Report, or		
NOT	ICE OF INTENTION TO:		QUENT REPORT OF:	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	PULL OR ALTER CASING   MULTIPLE COMPLETE   ABANDON*   CHANGE PLANS	(Norr: Report resul	REPAIRING WELL ALTERING CABING ABANDONMENT* CUS Report X ts of multiple completion on Well pietion Report and Log form.)	

Request one year extension to complete pilot flood study.

This approval of temponary NOV 1 1978 abandonment expires

.

18. I hereby certify that the foregoing is true and correct SIGNED _C. R. Korysawa	TITLE Project Petroleum Engineer DATE October 14, 1975
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE APPROV DATE
* <b>(</b>	See Instructions on Reverse Side ARTHUR R. BROWN ARTHUR R. BROWN