11 110 C C -	-	Budget Bureau No. 42-R358.4. Approval expires 12-31-60.
(Feb. 1051)	(SUBMIT IN TRIPLICATE)	Land Office LEAS CTUCES Lease No. LC 032573 b Unit NMFU

SUNDRY NOTICES AND REPORTS ON WELLS

	Subsequent Report of Sandfrac 1
NOTICE OF INTENTION TO ABANDON WELL	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF

Elliott B-7		-	November 22 , 1957			
Well No. 2 is located	1980 ft.	from 🙀 line	and 1980 ft. from 🕌 line of sec	7		
N3/4 Sec. 7 (% Sec. and Sec. No.)	229	37 5 (Range)	NMPM			
(1/2 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)			
Penrose-Skelly		Iea	New Mexico			
(Field)	(C	ounty or Subdivision)	(State or Territory)			

The elevation of the derrick floor above sea level is _3440 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Before Workover: TD Lime 3724', DF 10', elev 3440' DF. Pay Queen 3629-3724' open hole. Casing point 5 1/2" at 3629'. Flowed 2 bbls oil, no water, in 24 hrs, 25/64" choke, TP 50#, CP 300#, gas volume 26.7 MCFPD, GOR 13,350. DOR 2 bbls. Daily allowable 2 bbls oil. Work Done: Killed well w/oil, pulled tbg. Ran Gaama ray neutron log, found top of fill at 3678'. Ran and set tbg at 3583'. Sandfraced open hole 3629-3724' thru tbg and tubing-casing annulus w/10,000 gals crude w/1# sand and 0.1# Adomite per gal. Swabbed well in, failed to recover load by flowing. Shut well in. After Workover: TD Lime 3724', DF 10', elev 3440' DF. Pay Queen 3629-3724' open hole. Casing point 5 1/2" at 3629'. TSD. Failed to recover load. workover started 3-31-57, completed 4-4-57.

l understan	d that this plan of work must receive approval in writing	by the Geological Survey be	fore operations may be commenced.	
Company _	Continental Oil Company			
Address	6. 0. Box 68			
	aunice, New Mexico	Ву		-
		Title Distr	ict <u>superintendent</u>	-