STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT		
CITCITUT AND MINICHALS DEPARTMENT	··· .	
	L CONSERVATION DIVISION	
UIST A BUTTON	P. O. BOX 2088	Fore C 103
SANTA PE	SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fee D
OPERATOR		5. State Oil & Gas Lease No.
		·
IDO NOT USE THIS FORM FOR PROPOSALS TO DRILL	AND REPORTS ON WELLS	
I.	" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL CAS WELL OTHER.		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
William B. Yarborough		L. E. Grizzell
3. Address of Operator		9. Well No.
200 N. Loraine, Suite 1400 -	Midland, Texas 79701	1
B 660		10. Field and Pool, or Wildcat
UNIT LETTER D DOU_FEET	FROM THE NORTH LINE AND 1980 FEET FRO	Paddock
THE East LINE SECTION 8	TOWNSHIP22-SRANGE37-ENMP	
	TOWNSHIP Z_Z RANGE J/- E NMP)	· ())))))))))))))))))))))))))))))))))))
,	lovation (Show whether DF, RT, GR, etc.)	12. County
	3435 GR	Lea
Check Appropriate F	Box To Indicate Nature of Notice, Report or O	ther Data
NOTICE OF INTENTION TO	SUBSEQUEN	IT REPORT OF:
PERFORM REMEDIAL WORK		-
TEMPORARILY ABANDON	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PULL OR ALTER CASING	COMMENCE DRILLING OPNS.	PLUG AND ABAHOONMENT
	OTHER_	г
OTHER		
7. Describe Proposed or Completed Operations (Clearly	state all pertinent details, and give pertinent dates, includin	
		g estimated date of starting any propos
June 15 through June 21		
- RU well service unit. pull	rods and tubing, found seating nipple	
		at 4904
	UI 6	
- - GIH w/4 3/4" bit and scrape	UI 6	
- GIH w/4 3/4" bit and scraper circulating. POOH	916. r - max. depth 4902 - made no progress	s w/rotation and
<ul> <li>GIH w/4 3/4" bit and scraper circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal</li> </ul>	916. r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; '	s w/rotation and 'mule shoe" appears
<ul> <li>GIH w/4 3/4" bit and scraper circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below to</li> </ul>	916. r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5#" liner (3341 ft ), attaced to	s w/rotation and 'mule shoe" appears
<ul> <li>GIH w/4 3/4" bit and scrape circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below to questionable - could not go</li> </ul>	916. r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t	s w/rotation and 'mule shoe" appears to test casing - test
<ul> <li>GIH w/4 3/4" bit and scrape circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below to questionable - could not go</li> </ul>	916. r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t	s w/rotation and 'mule shoe" appears to test casing - test
<ul> <li>GIH w/4 3/4" bit and scrape circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below to questionable - could not go</li> </ul>	916. r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5#" liner (3341 ft ), attaced to	s w/rotation and 'mule shoe" appears to test casing - test
<ul> <li>GIH w/4 3/4" bit and scrape circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below to questionable - could not go</li> </ul>	916. r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t	s w/rotation and 'mule shoe" appears to test casing - test
<ul> <li>GIH w/4 3/4" bit and scrape circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below to questionable - could not go</li> </ul>	916. r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t	s w/rotation and 'mule shoe" appears to test casing - test
<ul> <li>GIH w/4 3/4" bit and scrape circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below to questionable - could not go</li> </ul>	916. r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t	s w/rotation and 'mule shoe" appears to test casing - test
<ul> <li>GIH w/4 3/4" bit and scrape circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below to questionable - could not go</li> </ul>	916. r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t	s w/rotation and 'mule shoe" appears to test casing - test
<ul> <li>GIH w/4 3/4" bit and scrape circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below to questionable - could not go</li> </ul>	916. r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t	s w/rotation and 'mule shoe" appears to test casing - test
<ul> <li>GIH w/4 3/4" bit and scrape circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below to questionable - could not go</li> </ul>	916. r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t	s w/rotation and 'mule shoe" appears to test casing - test
<ul> <li>GIH w/4 3/4" bit and scraper circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below f questionable - could not go</li> <li>Rig down well service unit a</li> </ul>	r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t deeper. and shut in for additional study and e	s w/rotation and 'mule shoe" appears to test casing - test
<ul> <li>GIH w/4 3/4" bit and scrape circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below to questionable - could not go</li> </ul>	r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t deeper. and shut in for additional study and e	s w/rotation and 'mule shoe" appears to test casing - test
<ul> <li>GIH w/4 3/4" bit and scraper circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below f questionable - could not go</li> <li>Rig down well service unit a</li> </ul>	r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t deeper. and shut in for additional study and e	s w/rotation and 'mule shoe" appears to test casing - test
- GIH w/4 3/4" bit and scraper circulating. POOH - GIH w/2 3/8" tbg w/"mule sho to have been on metal. - GIH w/packer and set below to questionable - could not go - Rig down well service unit a - Rig down well service unit a	r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t deeper. and shut in for additional study and e	s w/rotation and 'mule shoe" appears to test casing - test
<ul> <li>GIH w/4 3/4" bit and scraper circulating. POOH</li> <li>GIH w/2 3/8" tbg w/"mule sho to have been on metal.</li> <li>GIH w/packer and set below to questionable - could not go</li> <li>Rig down well service unit a</li> </ul>	r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t deeper. and shut in for additional study and e	s w/rotation and 'mule shoe" appears to test casing - test
- GIH w/4 3/4" bit and scraper circulating. POOH - GIH w/2 3/8" tbg w/"mule sho to have been on metal. - GIH w/packer and set below to questionable - could not go - Rig down well service unit a - Rig down well service unit a	r - max. depth 4902 - made no progress oe", wash w/rotation to 4909. POOH; ' top of 5½" liner (3341 ft.); attempt t deeper. and shut in for additional study and e	s w/rotation and 'mule shoe" appears to test casing - test

(Ap 1-1-89