

Indian Agency.....

(SUBMIT IN TRIPLICATE)

U. S. Land Office **Las Cruces.**Lease or permit No. **033706**
C.P. Falby

Allottee.....

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lease No.....

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Wink, Texas **November 11**, 19**37****C.P. Falby**Well No. **2** is located **660** ft. from **N** line and **660** ft. from **W** line of sec. **8****NW 1/4 of NW 1/4 Sec. 8** **22 S.** **37 E.** **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)**Penrose****Lea****New Mexico**

(Field)


(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is **3443** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set and cemented 3488' (113 Jts.) of 7"OD, 24#, 10thd., seamless casing at 3500' with 300 sacks of El Toro common cement. Completed cementing at 9:00 AM. 11-4-37.**Drilled plug at 1:00 AM. 11-11-37. Bailed hole dry, let stand one hour, tested OK; Hole dry.**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The Texas Company**Address **Drawer K.****Wink, Texas**

By

Title **District Superintendent**

