

(SUBMIT IN TRIPLICATE)

U. S. Land Office. Las Cruces  
Lease or permit No. 033706  
C.P. Falby (a) lease

.....  
Allottee.....  
Lease No.....  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<b>X</b>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Wink, Texas July 24, 1938

C.P. Falby (a)  
Well No. 3 is located 1980 ft. from N line and 1980 ft. from W line of sec. 8

SE<sub>1</sub>-NW<sub>1</sub> of Sec. 8 22-S. 37-E. N.M.P.M.  
( $\frac{1}{4}$  Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Penrose Area Lea County New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3422 ft.

**DUPLICATE**

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set and cemented 348' of 10-3/4"OD, lapweld casing at 373' with 300 sacks of El Toro common cement. Completed cementing at 5:30 PM. 7-21-38.


Drilled plug at 6:15 AM. 7-23-38; bailed hole dry; tested OK. Hole dry, after standing one hour.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Drawer K

Wink, Texas



By L. J. Shupert

Title District Superintendent