

(Nov. 1936)

Indian Agency.....

(SUBMIT IN TRIPLICATE)

U. S. Land Office.....

033706

Lease or permit No.....

C.P. Falby (a) lease.

Allottee.....

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lease No.....

SUNDRY NOTICES AND REPORTS ON WELLS

DUPLICATE

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	X	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Wink, Texas August 6, 1938

C.P. Falby (a)

Well No. 3 is located 1930 ft. from [N] line and 1930 ft. from [W] line of sec. 8

SE1-NW1 of Sec. 8
(1/4 Sec. and Sec. No.)22-S. 37-E
(Twp.) (Range)R.M.P.M.
(Meridian)Penrose Area.
(Field)Lea County
(County or Subdivision)New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3422 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth - 3540' Lime.

Set and cemented 3496' of 7"OD, 24#, seamless casing at 3514' with 300 sacks of cement. Completed cementing at 5:00 PM. 8-4-38.

Anticipate drilling plug and testing casing by pressure method after 60 hours or at approximately 5:00 AM. 8-7-38.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Drawer K

Wink, Texas

By

Title District Superintendent