

HUMBLE OIL & REFINING COMPANY

J. L. CRIMSON / L.

SE 1/4 of Section 9, Twp. 23-South, Range 37-East, Penrose Area  
Lea County, New Mexico.

\*\*DEVIATION SURVEYS\*\*

Acid bottle test at 650' deviation 1/2 degree  
Acid Bottle test at 1040' deviation 1/2 degree  
Acid bottle test at 1900' deviation 1/2 degree  
Acid bottle test at 2175' deviation 1/2 degree  
Acid bottle test at 2330' deviation 3/4 degree  
Acid bottle test at 2395' deviation 3/4 degree  
Acid bottle test at 2545' deviation 3/4 degree  
Acid bottle test at 2700' deviation 1/2 degree  
Acid bottle test at 3000' deviation 1/2 degree

BOTTLE OPEN TESTS

None.

