

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. 032573

Tract 258.26-8

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Elliott

June 8, 1946

Well No. 4-B is located 554 ft. from N line and 2084 ft. from W line of sec. 9

NW 1/4 section 9 22S 37E N.M.I.M.  
(1/4 Sec. and Sec. No.) Twp. Range Section

Brunson Lea New Mexico  
(Field) (County or subdivision) (State or Territory)


The elevation of the derrick floor above sea level is        ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings, indicate mudlogging jobs, cementing points, and all other important proposed work.)

13-3/8" forty eight pound casing was cemented with 200 sacks at 171 feet on June 5, 1946. Plug was pumped down at 4:30 P.M.

Cement was allowed 48 hours set time before plug was drilled and casing tested. Test proved cement job to be O.K.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company N. G. Penrose, Inc.

Address Ft. Worth, Texas

By [Signature]  
Title Agent