

Project Bureau No. 0-1000
Approval stamp 11-10-46

HOEBS OFFICE LOC. Las Cruces

(SUBMIT IN TRIPLICATE)

Lease No. 032573

UNITED STATES APR 23 AM 2:03
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 19, 1946

Well No. B9 #5 is located 660 ft. from N line and 2130 ft. from W line of sec. 9
NW 1/4 section 9 22S 37E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Brunson Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We cemented 32# 8-5/8" casing at 2749' with 800 sacks 2% aquagel cement and 400 sacks regular cement. Plug was pumped down at 12:00 midnight, September 16, 1946.

We tested casing and drilled cement at 4:00 A.M. September 19, 1946. Casing tested OK under pressure.

RECEIVED

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company N. G. Penrose, Inc.

Address Ft. Worth, Texas.

By L. G. Penrose

Title Agent