APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240	Box 1980, Hobbs, NM 88240 2040 Pacheco St.			WELL API NO. 30-025-10206 10 20 9		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			sIndicate Type of Leas		FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			₅State Oil & Gas Leas		· •v	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7Lease Name or Unit Agreement Name S. E. Long			
Type of Well: OIL GAS WELL WELL X	OTHER					
₂Name of Operator Titan Resources I, Inc.			8 8			
sAddress of Operator 500 West Texas, Suite 500, Midland, Texas 79701			Pool name or Wildcat Blinebry			
Well Location Unit Letter J 1650 For	eet From The South	Line and 2310	Feet From The	East	_ Line	
Section 11	Township 22S R	tange 37E	NMPM	Lea c	ounty	
to Elevation (Show whether DF, RKB, RT, GR, etc. 3350 DF						
11 Check App	propriate Box to Indicate Na	1	port, or Other SEQUENT RE			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING	i [
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OF			PLUG AND ANBAND	ONMENT [_]	
PULL OR ALTER CASING	CASING TEST AND CEME					
OTHER:		OTHER: Perf Blinebry			X	
12Describe Proposed or Completed Operations (work) SEE RULE 1103.	Clearly state all pertinent details, and give	pertinent dates, including es	timated date of starting	any proposed		
8/26/98 Swab, release pkr, TOH, se 8/27/98 TiH pkr, 1.78" profile nipple tag pkr @ 5895', latch on p 8/28/98 Frac Blinebry (5375'-5793') changed out collar, restart 8/29/98 Flowed back 34 BLW w/10' profile nipple 5218', RD side 10/28/98 Suppl. 105 PLW off hackside	dump 30' cmt on CIBP. (33 holes) 1 SPF, TIH pkr to 5795; FE w/100 bs, RU swab, swab dry et frac tanks, unload & rak 3 1/2" f , on/off tool, & tog, tested to 9000 pkr, pull up hole, set pkr @ 5218', Medallion 3500, start frqc, 190 bt , frac, 144,251# sand in form - 422 (roll cut overnight, turn well down)	s', spot 420 gals 15% N rac pipe on racks. psi, pkr would not set, load backside 2% KCL pls pad in, developed c 21#, n flowline, Ru wireline, t 5, LD 1 jt 3 1/2" tbg, RU 5, TiH on/off tool, 164 it	TOH, did not retried. TOH, did not retried. Ir leak underneath ag fill 5802', set 1. swab ws tbg. latch on ple	270' eve pkr, TIH on/off frac valve on 3 1/2 78" blanking plug i kr, ND BOP, NU w	2" tbg n	
I hereby certify that the information above is true						
SIGNATURE Shirley mal	to	rLE Engineering Tech		DATE 08-31-9	8	
TYPE OR PRINT NAME Shirley Melton				TELEPHONE NO. (915)498-8604	
(This space for State Use) ORIGINAL LIJUITED	AMALIJAMS Reducing Security			DATE OV ()	6 19 98	

__ TITLE ______