

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company OIL WELL DRILLING COMPANY				Address 614-617 Adolphus Tower, Dallas, Texas			
Lease Thomas Long	Well No. 4	Unit Letter L	Section 11	Township 22S	Range 37E		
Date Work Performed 3-31-60	Pool Drinkard			County Lea			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain): **Acid**
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Well was dead. Rigged up single drum unit and tools on 3-31-60 to swab fluid from 2" tubing to tank battery. Pumped 500 gallons of 15% mud acid down dry tubing and displaced with oil. Resulted in a 4 barrel increase of oil and the gas is about the same. 2/10 water still shows acid.

Witnessed by	Position	Company Halliburton J. P. (Bum) Gibbins, Inc.
--------------	----------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA


D F Elev. 3368.5	T D 6459	P B T D	Producing Interval 6423	Completion Date 1-23-50
Tubing Diameter 2"	Tubing Depth 6459	Oil String Diameter 5 1/2"	Oil String Depth 6421	
Perforated Interval(s) None - Packer set at 6423'				
Open Hole Interval			Producing Formation(s) Drinkard	

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover	3-19-60	4	112	Trace	14,030	
After Workover	4-20-60	8	112	Trace		

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name
Title	Position Lease Pumper
Date	Company OIL WELL DRILLING COMPANY