

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dual (Tubb Gas - Drinkard Oil)		7. Unit Agreement Name
2. Name of Operator Marathon Oil Company		8. Farm or Lease Name Edith Butler "B"
3. Address of Operator P. O. Box 2409, Hobbs, New Mexico 88240		9. Well No. 1
4. Location of Well UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>13</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> N.M.P.M.		10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) DF 3338'; GL 3326'		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Pipe casing bradenheads to surface</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Dug well cellar out to expose all casing bradenhead outlets.

Installed 1" piping from 2" valve on outlet on each bradenhead to a point above ground level. Installed 1" valve on upper end of piping.

Ran bradenhead pressure. Survey indicated no leak.

Piping arrangement, open position of 2" valve and closed position of 1" valve, inspected and approved by New Mexico Oil Conservation Commission Deputy Oil and Gas Inspector, Leslie Clements.

Bradenhead Size
13 3/8"
8 5/8"

Bradenhead
Valve Location (1")
East side of well
Southwest side of well

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Larry L. Rivers TITLE Petroleum Engineer DATE January 2, 1975

APPROVED BY _____ TITLE _____ DATE _____