

Las Cruces

(SUBMIT IN TRIPLICATE)

Land Office

Lease No. **LC 032573 b**

Unit

NMPU

			<b>X</b>

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<b>Subsequent Report of Sandfracture IX</b>	<b>IX</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

S Elliott 8-17

August 7, 1957

Well No. **1** is located **660** ft. from **[N]** line and **660** ft. from **[E]** line of sec. **17**

N 1/4 Sec 17

22 S 37 E

NMPU

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Fenrose-kelly

Lee

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is ..... ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Before workover: TD Sand 3700', of 10', elev 3404'. Pay Grayburg 3530-3700' open hole. Casing point 5 1/2" set at 3530'. TSD.

Work done: Pulled tubing, ran 2 1/2" log. Ran 2" tubing set at 3463'. Sandfractured open hole w/10,000 gals crude w/1% sand and 0.1% Adomite per gal.

After workover: TD Sand 3700', of 10', elev 3404'. Pay Grayburg 3530-3700' open hole. Casing point 5 1/2" set at 3530'. Flowed 4 bbls oil, no water, in 24 hrs. 20/64" choke, TP 100#, CP 200#, gas volume 80 MCFPD. GOR 20,000. GOR 4 bbls, daily allowable 4 bbls oil.

Workover started 4-7-57, completed 8-2-57, tested 8-2-57.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Continental Oil Company**Address **Box 68****Unice, New Mexico**

By

Title **District Superintendent**