

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. OIL CONS. COMMISSION
P.O. BOX 1980
HOBBS, NEW MEXICO 88400

5. Lease Designation and Serial No.
LC 034548

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No. RUBY CROSBY
WELL NO. 1

9. API Well No.
30-025-10356

10. Field and Pool, or Exploratory Area
EUMONT, YTS, 7RV, QN

11. County or Parish, State
LEA COUNTY, NM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

MERIDIAN OIL INC.

3. Address and Telephone No.

P.O. Box 51810 Midland, TX 79710

915-688-6943

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

C, 660' FNL & 1650' FWL

SEC. 18, T22S, R37E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11/21/93: MIRU. PMP STUCK. STRIPPED OUT OF HOLE. RIH W/CICR TO 3250'. LEFT SWINGING.

11/22/93: SET CICR AT 3230'. SQZD 50 SXS CMT BELOW. STUNG OUT. CAPPED W/6SXS. CIRCULATED HOLE W/MUD. PU TO 2488'. SPOT 25 SXS. PU TO 1254'. SPOT 25 SXS. PU TO 356'. PMPED 35 SXS. CIRCULATED TO SURFACE. ND BOP.RDMO. CUT OFF WELLHEAD 3' BELOW SURFACE. INSTALLED P & A MARKER.

LOCATION HAS NOT BEEN CLEANED AS OF THIS DATE. WILL FILE FOLLOWUP SUNDRY UPON COMPLETION OF CLEANUP.

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed

DONNA WILLIAMS

Title PRODUCTION ASSISTANT

Date 11/29/93

(This space for Federal or State office use)

Approved by

(ORIG. SGD.) JOE G. LARA

Title PETROLEUM ENGINEER

Date 12/13/93

Conditions of approval, if any: