

## NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103  
(Rev 3-55)

## MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

1961 AUG 1 AM 9:07

Name of Company <b>Skelly Oil Company</b>		Address <b>Box 38 - Hobbs, New Mexico</b>					
Lease <b>Hobbs "M"</b>	Well No. <b>1</b>	Unit Letter <b>"L"</b>	Section <b>20</b>	Township <b>22-S</b>	Range <b>37-E</b>		
Date Work Performed	Pool <b>Eumont</b>			County <b>Lea</b>			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☒ Casing Test and Cement Job
 ☐ Other (Explain):  
☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Set 10 jts. (286') of new 8-5/8" OD 24# 8-R SS J-55 RT&C casing at 298' and cemented with 250 sacks by the Halliburton Pump & Plug Process. Cement circulated to surface. Plug down at 1:30 A.M. July 25, 1961. W.O.C. 24 hrs. Pressured up to 600# for 30 mins. and casing tested OK. Drilled out cement plug and pressured up to 600# for 30 mins. and casing shut off tested OK.

Witnessed by <b>R. L. Calhoun</b>	Position <b>Dist. Foreman</b>	Company <b>Skelly Oil Company</b>
--------------------------------------	----------------------------------	--------------------------------------

## FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

## ORIGINAL WELL DATA


D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

## RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

## OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name (ORIGINAL SIGNED) <b>H. E. Aob</b>
Title	Position <b>Dist. Supt.</b>
Date	Company <b>Skelly Oil Company</b>