NUMBER OF COPIE			_							<u> </u>	
DIS" SANTA FE FILE				IEW MFT		L CO	NSER	ATION C	OMMIS	SION	FORM C-103
U.S.G.S.	OIL							ORTS ON			(Rev 3-55)
TRANSPORTER PRORATION OFFIC	GA5		(Subm				4	as per Comn			
Name of Compa						Address		100 0	<u>61 (</u>		
Socony M		Compan	y, Inc.	Well No.	Unit I			Hobbs, I	New Mex	Range	
Will Cary	·	r-		3			21	22.3			7 5
Date Work Perf. 4/26/63	ormed	P	Langlis	Mattix				County Lea			
				A REPOR	RT OF: (Check a	ppropria	te block)			
Beginning Drilling Operations Casing Test and Cem											
Plugging] Remedial Work				Casing Inspection			
Detailed accou	nt of work de	one, natu	re and quantity	of materia	ls used, a	and resu	lts obta	ined.			
Witnessed by A. H. JOL D F Elev.	nər	TD	FILL IN BE	LOW FO	luction	MAL W	ORK R		NLY	Oil Comp	any, Inc.
Tubing Diame	Tubing Diameter T		Tubing Depth		Oil String Di		ng Diam	iter Oil		String Depth	
Perforated Int	erval(s)						<u></u> .				·····
Open Hole Int	erval				1	Produci	ng Form	ation(s)	<u></u>	<u></u>	
				RES	ULTS OF	WORI	OVER				
Test		Date of Oil Prod Test BP		tion Gas Production MCFPD			Water Production BPD		GOR Cubic feet/Bbl		Gas Well Potential MCFPD
Before Workover											
After Workover											
		ISERVAT	ION COMMISSI	ON		I here to the	eby cert e best o	ify that the in f my knowled,	nformation ge.	n given abov	e is true and comple
Approved by	Fo. 1	1.	\$172	line	A	Name		mei	har.		
Title	Juli			lml	ut_	Posit	. 1	pervisor	<u>u i i i i</u>	<u>(~1</u>	<u> </u>
Date		<u> </u>				Comp	any	÷			
[So	ony 3	obil 011	Compa	ny, Inc.	