

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Budget Bureau NO. 1004-0155
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

71-032573-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

E.M. Elliott Fed.

8. FARM OR LEASE NAME

E.M. Elliott Fed

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

McCormick Silurian, So.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 22, TS22S, R37E

12. COUNTY OR PARISH 13. STATE

Lea

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Arch Petroleum Inc.

3. ADDRESS OF OPERATOR

Suite IIA, 777 Taylor Street, Fort Worth, Texas 76102

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

UNIT D, 330' FNL and 990' FWL, SEC. 22, TS 22S, RNG. 37E,
Lea County New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3379GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) Install Artificial Lift

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Change Operator: Old, Carter Foundation Production Co. New, Arch Petroleum Inc. 1 Feb. 89

Install Artificial Lift

4-11-89 MIRU Pool Well Service

Tested casing to 500#

Pulled tubing and laid down Mod. R Packer

Tested tubing to 6000#

Ran 1jt. mud anchor, 4' perf. sub, SN, 5jts 2 3/8, tubing anchor and 22ljts of 2 3/8. SN @ 6969'

4-12-89 Ran 2X1 1/2 X 16 pump, 16 7/8, 172 3/4 87 7/8 rosd, 16X7/8 pony.
Hung well on. Started pumping 6:00PM.

18. I hereby certify that the foregoing is true and correct.

SIGNED Jim B. Paschall

817 332 9209

TITLE V. P. Operations

DATE 5-23-89

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side