

DIAGRAMMATIC SKETCH OF  
PREPARED HUAL COMPLETION  
ROMAN OIL CO. NO. 1 WELL CARRY  
SE/4 OF NW/4, SEC. 22, T-22-S, R-57-E.  
LEA Co., NEW MEXICO

5400

5500

PREPARED PERFORATIONS  
FROM 5475 - 5550 -

5600

CASED  
STRENGTH CHECK (SURVEY)

5700

PRODUCTION PACKER  
AT 5700'

6200

6300

REMARKS PERFORATIONS

6400

TRUBING AT 6425'

TRUBING AT 6410'

TRUBING AT 6427'