O. COPIES RECEIVED				form C-1		
D TRIBUTION					Supersedes Old C-102 and C-103	
T FE	N	NEW MEXICO OIL CONSERVATION COMMISSION			1-1-65	
s.G. 5.					Type of Lease	
LAND OFFICE				State X	Fee	
OPERATOR				5. State Oil 6	Gas Lease No.	
				NMJ 524	8	
SI	INDRY NOTICE	S AND REPORTS ON	WELLS			
(DO NOT USE THIS FORM F USE "AP	OR PROPOSALS TO DRI PLICATION FOR PERMI	ILL OR TO DEEPEN OR PLUG B	WELLS ACK TO A DIFFERENT RESERVO! H PROPOSALS.)	F. ()		
				7. Unit Agree	ement Name	
OIL GAS WELL WELL	DTHER-					
2. Name of Operator				8, Farm or Le	ease Name	
Texas Pacific Oil	Company, Inc	L		Boyd		
. Address of Operator				9. Well No.		
P. O. Box 4067, Midland, Texas 79701					4	
4. Location of Well					in. Field and Pool, or Wildcat	
UNIT LETTER	. 660 FE	ET FROM THE North	LINE AND	FEET FROM LEDS	lie Mattix	
ONTI ELITAR						
THE East LINE,	SECTION 23	TOWNSHIP	RANGE 37-E	NMPM. (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		
(HE						
	15	. Elevation (Show whether	DF, RT, GR, etc.)	12. County		
		3332 GR		Lea	<u> </u>	
^{16.} Ch	eck Appropriat	e Box To Indicate N	ature of Notice, Repo	ort or Other Data		
	OF INTENTION		_	SEQUENT REPORT	OF:	
,,,,,,						
PERFORM REMEDIAL WORK		PLIG AND ABANDON	REMEDIAL WORK	A	LTERING CASING	
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.	PL	UG AND ABANDONMENT	
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT JO			
POCE ON ALTER CASING			OTHER Repair S	alt water flow		
OTHER						
17. Describe Proposed or Comple	eted Operations (Cle	early state al! pertinent det	lails, and give pertinent dates	s, including estimated date	e of starting any proposed	
work) SEE RULE 1103.		•				
1. Dug pit and ha	mled water d	luring repair ope	erations.			
2. Installed class	pp on 13 3/8"	' surface casing	hole.			
•						
3. Pumped 400 sec	ks Helliburt	ton Lite cement of	lown 8 5/8" casing	g; circulated 10	sacks	
to pit through	13 3/8" sus	face casing.				
•						
4. Closed 13 3/8"	casing valv	re. Pumped addit	tional 80 sacks co	ement down 8 5/8	" casing.	
5. Closed 8 5/8"	casing valve	. Pumped addit:	ional 120 sacks co	ement down 13 3/	8" casing.	
6. Shut in overni	ight. Water	flow stopped.				
Work complete	7-8-74.					
•						
18. I hereby certify that the info	rmation above is tru	e and complete to the best	of my knowledge and belief.			
Original Sig		•				
T.lord tr						
	med by	Ar	es Superintendent		7-12-74	
SIGNED	right	TITLE AT	ea Superintendent	DATE	7-12-74	
SIGNED	right	TITLE AT	sa Superintendent	DATE	7-12-74	
SIGNED	right	TITLE AT	ea Superintendent	DATE	7-12-74	

CONDITIONS OF APPROVAL, IF ANY: