Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II			30-025-10500	
1301 W. Grand Ave., Artesia, NM 83210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE X	
District IV	Santa Fe, NM 87505		6. State Oil & 0	Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Annie L. Christm	nas
PROPOSALS.)	(,			
1. Type of Well:				
Oil Well Gas Well Other Disposal 2. Name of Operator			8. Well No. 3	
Yale E. Key, Inc.			o. Well No.	
3. Address of Operator			9. Pool name or Wildcat	
P.O. Box 2040 Hobbs, NM 88241			SWD San Andres	
4. Well Location				
Unit LetterB : _330feet from theN line and2310feet from theEline				
Section 28	Township 22S	Range 37E	NMPM	County Lea
	10. Elevation (Show whether I			
	ppropriate Box to Indicate		-	
NOTICE OF IN			SEQUENT RE	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K 📙	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST A	ND 🗆	
	_			_
OTHER:		<u>'</u>	ir and Maintenance	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of				
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.				
recompliation.				
2/24/03 RU pulling unit. Install BOP. Lay down 3820ft. 2 3/8 tubing. Did not get out with packer. Shut down				
2/25/03 Run 2 7/8 work string in hole with overshot and grapple. Did not get fish. Went back in hole with spear and retrieved packer.				
Shut down. 2/26/03 Run 2 7/8 work string back in hole and came out laying down. Tested 2 3/8 plastic lined pipe back in the hole 15 joints at time				
with burster plate on bottom. Rice Engineering supervised running tubing to insure plastic lining was intact and seal rings were correctly				
installed and proper torque applied to threads. Tubing tested O.K. and burster plate burst at 3500 lbs. Shut down.				
2/27/03 Pumped 100 bbls. Packer fluid. Remove BOP, set new 5"nickel plated Baker loc set packer and installed well head. Tested casing to 450#. Held O.K. Witnessed by OCD chart attached. RD pulling unit and put well back to injection.				
casing to 450#. Held O.K. Witnessed	by OCD chart attached. RD pul	lling unit and put we.	Il back to injection.	
			_	\ \}
			7.	all's
			Š	8,0,00
				10000 C
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE CAPE (rowelf TITLE	_Compliance Specia	alist	DATE2/28/03
Type or print name Royce Cro	well			Telephone No.393-9173
(This space for State use)	ORIGINAL SIGNED BY			V (5 A x 5000
APPPROVED BY	GARY W. WINK TITT IT		CER	M/R 0 4 2003 DATE
Conditions of approval, if any:	GARY W. WINK TITLE OC FIELD REPRESENTATION	VE II/STAFF MANA	OLF	_DATE

