

Submit 3 Copies  
to Appropriate  
District Office

District I

P.O. Box 1980, Hobbs, NM 88240

District II

P.O. Drawer DD, Artesia, NM 88210

District III

1000 Rio Brazos Rd. Aztec, NM 87410

State of New Mexico  
Energy, Minerals and Natural Resources Department

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

Form C-103  
Revised 1-1-89

WELL API NO.	30 - 025 - 10532 ✓
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL <input type="checkbox"/> WELL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> OTHER INJECTION	7. Lease Name or Unit agreement Name  SKELLY PENROSE B UNIT
2. Name of Operator OXY USA INC.	8. Well No. 12
3. Address of Operator P.O. Box 50250 Midland, TX 79710	9. Pool name or Wildcat LANGLIE MATTIX 7 RVR Q-GB
4. Well Location Unit Letter <u>P</u> ; <u>330</u> Feet From The <u>SOUTH</u> Line and <u>330</u> Feet From The <u>EAST</u> Line Section <u>31</u> Township <u>22 S</u> Range <u>37 E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,301	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: TEMPORARILY ABANDON ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3798' PERFS - 3677' - 3739'

MIRU PU 4/30/93, NDWH, NUBOP, POOH W/ TBG & PKR. RIH W/ WS TBG & TAG @ 3458'. CLEAN OUT TO 3757' & SET PKR @ 3610'. CSG DID NOT TEST, TOP OF BAD CSG @ 3429'. POOH W/ PKR & TBG. RIH W/ CIBP & SET @ 3400'. CIRCULATE HOLE W/ CORR INHIB, POOH W/ TBG, NDBOP, NUWH W/ 1JT 2-3/8" TBG & VALVE. TEST CSG TO 500# - 30 MIN - HELD OK, RDPV 5/4/93. WELL IS TA'D.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 05 13 93  
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915 685-5717


(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary  
Abandonment Expires 5-1-93


MAY 20 1993



S-4-93  
McCASLAND SERVICES  
Unit #49 Robt English

~~BOOK #~~

RECEIVED  
JUN 10 1993



RECEIVED  
MAY 1 9 1993  
CONTRACTS OFFICE

~~XXXXXXXXXX~~

5-4-93  
McCasland Services  
Unit #49  
Hickory Hill