

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Dalport Oil Corporation, 930 Fidelity Union Life Bldg. Dallas, Texas
(Address)

LEASE E. F. King "A" WELL NO. 2 UNIT I S 31 T 22-S R 37-E
DATE WORK PERFORMED 1 - 11 - 59 POOL

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☐ Other

Detailed account of work done, nature and quantity of materials used and results obtained.

Cemented 314' - 8 5/8" - 24# J-55 Seamless casing with 200 sacks cement.
Cement circulated. Tested with 600#s before and after drilling plugs.
Tested O. K.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. TD PBD Prod. Int. Compl Date
Tbng. Dia Tbng Depth Oil String Dia Oil String Depth
Perf Interval (s)
Open Hole Interval Producing Formation (s)

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test	<u></u>	<u></u>
Oil Production, bbls. per day	<u></u>	<u></u>
Gas Production, Mcf per day	<u></u>	<u></u>
Water Production, bbls. per day	<u></u>	<u></u>
Gas-Oil Ratio, cu. ft. per bbl.	<u></u>	<u></u>
Gas Well Potential, Mcf per day	<u></u>	<u></u>
Witnessed by <u></u>		

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name [Signature]
Title
Date

Name W. F. T. [Signature]
Position President
Company Dalport Oil Corporation