



(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. LC 063454

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 10, 1956

Lockhart
Well No. 1a2 is located 660 ft. from [N] line and 660 ft. from [E] line of sec. 5
NE 1/4 of Sec. 5 22S 38E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Leon New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3399 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The following program was used to plug and abandon this well:

Ran 15 sack cement plug from 10,954 to TD;
Ran 20 sack cement plug from 10,540 to 10,605.
Ran 20 sack cement plug from 8,160 to 8,225.
Ran 25 sack cement plug from 2,780 to 2,860.
Ran 10 sack cement plug at surface.

Erected 4" x 8" pipe marker properly inscribed.

Will notify the U.S.G.S. by phone when location is made and ready for final inspection.

9/13/56 Location Inspected & is OK. HED

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Neville G. Penrose Inc.

Address Box 988

Eunice, New Mexico

By Millard Deck

Title Asst. Prod. Supt.