(Revised 3-55) SION S on Rule 1106) Midland,Texas
on Rule 1106)
Midland, Texas
18 T 22-8 R 38-E
ard
ts of Test of Casing Shut-o
dial Work

Pulled rods and tubing. Acidize down 2" Tubing with 1,000 gals 15% NEA. Treated open hole from 6222! to 7142!. Pulled tubing. Acidize down 5 1/2" casing from 6822! to 7142! with 20,000 gals gelled acid and 20,000 lb sand. Complete 11:50 A.M. 11-11-58. Shut in 18 hours. Ran tubing. Swab well. Ran 3 1/2" sand pump. Checked cavings. 260' cavings in hole. Unable to clean out with sand pump. Clean out hole 6880' to 7030', 6992' to 7142' wash open hole 7116' to 7142'. Pulled 2" Tubing. Recovered load oil. Test and return well to production.

FILL IN BELOW FOR REMEDIAL WORK REPO	RTS ONLY	······
Original Well Data:		
DF Elev. 3364 TD 7142 PBD None Pro	od. Int. 6822 to 7143 om	pl Date 11-15-53
Tbng. Dia 2 Tbng Depth 6820 Oil Strip	ng Dia 51/2" Oil Str	ing Depth 6822:
Perf Interval (s) None		
Open Hole Interval 6822 to 7142 Producing Fo	rmation (s) Drinkerd	
RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	10-1-58	12-15-58
Oil Production, bbls. per day	6	22
Gas Production, Mcf per day		
Water Production, bbls. per day		3
Gas-Oil Ratio, cu. ft. per bbl.	=	1455
Gas Well Potential, Mcf per day	-	32
Witnessed by		
	(Company)	

Name	Men Marghall
Title	
Date	•

Name Position

Company The Texas Company