

(SUBMIT IN TRIPLICATE)

U. S. Land Office **Las Cruces**

Lease or permit No. **032104**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Midland, Texas** **January 29**, 19 **45**

**A. H. Blinebry**  
Well No. **1** is located **660** ft. from **S** line and **1980** ft. from **E** line of sec. **19**  
**SW 1/4 Sec. 19** **22-S** **38-E** **N.M.P.M.**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Ferrose** **Lee** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3357** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**Total Depth 300' - Red Beds**

**Set and cemented 276' of 13-3/8" casing at 293' with 360 sacks. Completed at 4:00 P.M. 1-24-45.**

**Drilled plug at 4:00 P.M. 1-27-45 and tested casing by pressure method using 1000" pressure. Tested O. K.**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The Texas Company**

Address **Box 1270**

**Midland, Texas**

By \_\_\_\_\_

Title **District Superintendent**