

(SUBMIT IN TRIPLICATE)

U. S. Land Office Las Cruces

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Lease or permit No. 032104

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas January 25, 19 45

A. H. Blinebry

Well No. 1 is located 660 ft. from [S] line and 1980 ft. from [E] line of sec. 19

SW 1/4 Sec. 19 22-S 38-E N. 40. 00. W.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Penrose Lea County New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3357 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth 300' - Red Beds

Set and cemented 276' of 13-3/8" casing at 293' with 300 sacks.  
Completed at 4:00 P.M. 1-24-45.

Anticipate drilling plug and testing casing by pressure method  
using 1000 pressure after 72 hours or at approximately 4:00 P.M.  
1-27-45.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Box 1270

Midland, Texas

By [Signature]

Title District Superintendent