(June 1990) DEPARTM	NITED STATES IENT OF THE INTERIOR OF LAND MANAGEMENT	M. OIL CONS. COMMINDION O. BOX 1980 HOBBS, NEW MEXICO 98240 FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals		5. Lease Designation and Serial No. LC 032104 6. If Indian, Alottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
2. Name of Operator		8. Well Name and Number BLINEBRY, A. H. FEDERAL NCT-1
TEXACO EXPLORATION & PRODUCTION INC.		10
3. Address and Telephone No. P.O. BOX 730, HOBBS, NM 88240 397-0426		9. API Well No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		30 025 12142
Unit Letter D : 660 Feet From The NORTH Line and 660 Feet From The		10. Field and Pool, Exploratory Area BRUNSON SAN ANDRES, EAST
WEST Line Section 20	Township <u>22S</u> Range <u>38E</u>	11. County or Parish, State LEA , NEW MEXICO
Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data		port, or Other Data
TYPE OF SUBMISSION	TYPE OF ACTION	
 Notice of Intent Subsequent Report Final Abandonment Notice 	Abandonment Recompletion Plugging Back Casing Repair Altering Casing OTHER: EXTEND TA STATU	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection S Dispose Water Note: Report results of multiple completion on Wet
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*. Texaco requests an extended TA status for the above well. The following procedure to test casing and plug integrity was performed 1/23/95.		
1. Pressure tested casing and plug with 500 psi for 30 min <held>. Test was witnessed by Pat Hutchins of the BLM 1/23/95.</held>		
Classify well to TA status. The original pressure chart was sent to the NMOC	CD and a copy can be found on the reverse side of this for	m.
Justification: Given the good size and condition of the wellbore and the particular location of the Blinebry #/0 Texaco is currently		
The standard one year time period for TA status should be adequate time for thorough evaluation.		
)	APPROVED 13 MONTH	
	ENDING	U BA G
14.1 hereby certify that the foreforing a true wet forecome SIGNATURE		
SIGNATURE TITLE Engineering Assistant DATE 3/29/95		
(This space for Federal or St. (ORNA. SQD.) JOE (APPROVED BY	. LARI ETROLEUM EN SI	N ARH
CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE
Title 18 U.S.C. Section 1001, makes it a crime for any person kn representations as to any matter within its jurisdiction.	owingly and willfully to make to any department or agency of the United S	itates any false, fictitious or fraudulent statements or





۱.,»

1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 -1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 -1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - ~

OFFICE