

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 032104

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas, February 6, 1946

A.H. Blinebry
Well No. 3 is located 1980 ft. from N line and 1980 ft. from E line of sec. 29
SE 1/4 NW 1/4 22-3 38-E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Drinkard-Yesso Lee New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3382 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth, 6995'-Anhydrite.

Set and cemented 6881' of 7" OD 23# seamless casing at 6893' with 500 sacks of cement. Completed cementing at 12:01 A.M. 1-21-46.

Drilled plug at 10:00 A.M. 1-21-46. Tested casing, using 1000# pressure, before and after drilling plug. Tested O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company THE TEXAS COMPANY

Address BOX 1270

MIDLAND, TEXAS

By [Signature]
for
Title District Superintendent.

1. The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that proper record-keeping is essential for the integrity of the financial system and for the ability to detect and prevent fraud.

2. The second part of the document outlines the specific procedures for recording transactions. It details the steps involved in the accounting cycle, from identifying the transaction to posting it to the appropriate ledger account. It also discusses the importance of double-checking entries to ensure accuracy.

3. The third part of the document addresses the issue of reconciling accounts. It explains how to compare the company's records with the bank's records to identify any discrepancies. It provides a step-by-step guide for performing a bank reconciliation and discusses the common reasons for differences between the two sets of records.

4. The fourth part of the document discusses the importance of internal controls. It describes various control measures that can be implemented to reduce the risk of errors and fraud, such as segregation of duties, authorization requirements, and regular audits. It also discusses the role of management in establishing and maintaining a strong internal control system.

5. The fifth part of the document discusses the importance of financial reporting. It explains how financial statements are prepared and how they are used by management and external stakeholders to make informed decisions. It also discusses the importance of transparency and accuracy in financial reporting and the consequences of providing misleading information.

6. The final part of the document provides a summary of the key points discussed throughout the document. It reiterates the importance of accurate record-keeping, proper accounting procedures, reconciliation, internal controls, and financial reporting in maintaining the integrity of the financial system.