



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 063228
Unit I

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
<u>Notice of Intention to perforate additional pay</u> x	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 16, 1963

Fields

Well No. 1 is located 1650 ft. from DR line and 330 ft. from E line of sec. 24

NE/4 SE/4 Sec 24 23S 32E NMFM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Cruz Delaware Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3719 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 5168'. Casing Point, 4 1/2" at 5168'. Perforations 5101-5105 Ramsey Sand. The well averaged 19 BOPD during August, 1963. In order to increase production, it is proposed to clean out sand and perforate additional Ramsey Sand interval 5105-5112, and test natural. If natural test indicates treatment of formation is needed, will frac with approximately 3000 gallons.

A subsequent report will be filed upon completion of the above work.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company H. L. Johnston, Sr.

Address 1901 South Heights Drive

Roswell, New Mexico

By W. M. Moore

Title Accountant