

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
reverse side)FD-
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

A.H. Blinebry Fed (NCT-4)

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Blinebry Oil

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 31, T-22-S, R-38-E

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3343' (DF)

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Temp Abandon

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

REMARKS

1. Well Status - Shut-In
2. Temporary Abandonment Date - 9-18-75
3. Reason for Abandonment - Junk in the hole and near depletion of Blinebry.
4. Future Plans - Evaluate to complete in the Tubb (Gas) or to DHC Blinebry and Drk. and to clean out junk in the hole.
5. Date of Future Workover or Plugging - 9-76

This approval of temporary
abandonment expires OCT 1 1976

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Asst. Dist. Supt.

DATE 1-16-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: