

Petroleum Building Suite 200 P.O. Box 2523 Roswell, New Mexico 88202, USA Telephone (505) 622-2202 FAX (505) 622-2297

Siete has not receive a deviation survey report from McGee Drilling yet. Listed below are the deviations called in daily by the rig. When we receive the formal surveys from McGee I will forward them on to you.

> 1° @ 6455' 1° @ 6485' 1° @ 6980' 1½° @ 7480' 1½° @ 7598' 1° @ 8081' 1° @ 8300'

Thank you.

SIETE OIL AND GAS CORPORATION

ΒY Cathy Batley-Seely Reg. Spec.

cc:file