

	<b>X</b>		

R. W. STANLEY  
DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office **Las Cruces**Lease No. **062887**Unit **C**

MAY 1963

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<b>X</b>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Wehrli

April 26, 1963, 19

Well No. **1** is located **990** ft. from **N** line and **2310** ft. from **W** line of sec. **25****NE/4 NW/4 Sec 25**  
(1/4 Sec. and Sec. No.)**23S**  
(Twp.)**32E**  
(Range)**NMPM**  
(Meridian)**Undesignated**  
(Field)**Lea**  
(County or Subdivision)**New Mexico**  
(State or Territory)The elevation of the derrick floor above sea level is **3719** ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Subject well was drilled to a TD of 5151' (corrected by log) in the Delaware Sand Formation. No oil or gas was encountered in commercial quantities.

Permission is requested to plug and abandon the subject well. The well contains 638' of 7 5/8" 26# J-55 casing set at 638'. It is proposed to plug the well in the following manner: Place cement plugs at following intervals, 5151-5051', 4834-4734' base of salt, 1409-1309' top to salt, 700-600', and 10 sack plug at surface. A 4" x 4' steel marker will be erected on the well site and location will be restored to original condition. A subsequent report will be filed upon completion of the above work. This procedure was approved by Elmo Huddle in the USGS office, Hobbs, New Mexico, in conversation with Charlie Snure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Hugh L. Johnston, Sr.**Address **1901 South Heights Drive**  
**Roswell, New Mexico**

By

Title

**Owner**

USGS (5) WRH File