

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other

2. NAME OF OPERATOR
ESTORIL PRODUCING CORPORATION

3. ADDRESS OF OPERATOR
11th floor, Vaughn Bldg.

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 660' FSL & 1830' FWL of Sec.
AT TOP PROD. INTERVAL: 22
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

☐
☐
☐
☐
☐
☐
☐
☐

(other) PROGRESS REPORT

5. LEASE
NM 0552659 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
CURRY FEDERAL

9. WELL NO.
TWO

10. FIELD OR WILDCAT NAME (UNDESIG.
ANTELOPE RIDGE-MORROW GAS)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

SEC. 22, T23S, R34E

12. COUNTY OR PARISH 13. STATE
LEA NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3476' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-3-82 RU WL unit. Set plug & prod. Pkr. Open sliding sleeve in tbg. string. Circ. hole clean w/10# brine wtr. MI PU, ND tree, NU BOP, pulled & LD 200 jts. 2-7/8" tbg.

8-4-82 Finish pulling up. LD 2-7/8" tbg. RU WL unit. Ran dump bailer. Capped pkr w/35' cmt. New PBTD 11,889'. RU perf. gun. Perfed. 5.5" csg. @ 11,030'. Attempt to circ. 5.5" & 7-5/8" csg. w/neg. results. Perf. 5.5" csg. @ 10,900'. Attempted to circ. between 5.5" & 7-5/8" csg. w/neg. results. RD WL unit. RD PU.

Subsurface Safety Valve: Manu. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED DAVID R. GLASS TITLE PROD. CLERK DATE 8-10-82


APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
(ORIG. SGD.) DAVID R. GLASS

OCT 14 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side



ROSWELL, NEW MEXICO

RECEIVED

OCT 15 1982

O.C.D.
HOBBS OFFICE