

WORKOVER - RECOMPLETION RECORD		RECOMPLETION WO# VER P & A		DISTRICT Midland - West	A.F.E. NO. 71036
WELL NAME AND NUMBER Elliott B-20 #1		FIELD Langlie Mattix 7 Riv On		STATE N. Mexico	
LOCATION		COUNTY Lea		DATE STARTED 10-7-75	
CONTRACTOR		T.P. WELL 62.50%		DATE COMPLETED	
PRODUCTION BEFORE WORKOVER & OR RECOMPLETION			PRODUCTION 30 DAYS AFTER WORKOVER RECOMPLETION COMPLETED		
OIL OR DIST. BBLs	GAS MCF	WATER BBLs	OIL OR DIST. BBLs	GAS MCF	WATER BBLs
IF RECOMPLETION-ZONE, PERFORATIONS					
NATURE OF WORK (TREATMENTS, ETC.) Cement across WI zone					
SIGNED				DATE SIGNED	

CHRONOLOGICAL HISTORY

ELLIOTT B-20 NO. 1 -----INITIAL REPORT----- AFE NO. 71036
 TPWI 62.50%. LANGLIE MATTIX/7 RIV ON OIL. LEA COUNTY, NEW MEXICO
 AFE TO RE-CEMENT ACROSS WI ZONE.

10-7

RUNNING TBG & RBP.
 RU PU. UNSEAT PUMP & HOT OIL TBG. POH W/RODS. INSTALL
 BOP. POH W/TBG. MI FRAC TANKS & LOADED W/WTR. SDON.

10-8

RNG TBG W/DC'S & BIT. WOC.
 RAN TBG W/RBP, SET @ 3007'. TST TO 1500#, HELD OK.
 RU DRESSER & DUMPED 2 SX SD ON RBP. PERF 4 HOLES 2350-51 W/3-1/8"
 CSG GUN W/.66" HOLES. PRESSURED TO 1500#, COULD NOT PMP IN. PERF
 4 HOLES @ 2200' (PER NMOCC RECOMMENDATION) PMPD IN 3 BPM @ 1700#.
 RAN TBG W/CMT RET & SET @ 2120'. PMPD 50 BBLs BRINE, COULD NOT
 ESTABLISH CIRC. PMPD 860 SX HOWCO LIGHT, CMT TRUCK BROKE DOWN.
 PMPD 4 BPM @ 2000#. LACKED 40 SX PMPG ALL HOWCO LIGHT, DID NOT
 PMP ANY CLASS "C". REV OUT CMT, POH W/TBG. RAN TEMP SURVEY
 AFTER 12 HRS, TOC 1610'.