

WELLFILE CONTACT INFORMATION

OPERATOR NAME: Dawson Oper. / Llano
WELL ID: 25-24511
N.M. 'M' #87

DATE CALLED: 6-13-95
PERSON CONTACTED: Jim Dawson
LOCATION: Mid Lx
PH. #: 915-682-3737

REASON FOR CONTACT: 'Review' file: Has
unsuccessfully recompleted in
galmat. Back to L-17 & S1
status. Will send approp.
forms.

LETTER: YES ☒ NO MAILED: _____

ATTN TO: _____

LOCATION: _____

INITIAL: JD