




GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

R.A. Oilfield

SOUTH
UNIT

EUNICE
65

UNIT # 14
700
2-6 1991

BR 2221

South. Exper. Unit # 65.

2-6-91.

Test CS9 to 500 # for 15 min
Held.

4 1/2 Baber. Loh set. Pkr. @ 3520'