WELL NAME AND NUMBER _____ South Penrose Skelly Unit #262____

LOCATION 1300' FSL & 1139' FEL Section.8, T-22S, R-37E, Les County, New Mexico (New Moxico give U,S,T & R; Texas give S,Blk.,Sur.& Twp.when required)

OPERATOR GULF OIL CORPORATION

DRILLING CONTRACTOR Cactus Drilling Company

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above-described well and that he has conducted deviation tests and obtained the following results:

Degreos	a @ Depth	<u>1</u> .	Degrees @ Depth	1	Degrees	@ Depth		Degrees	a Depth
1/4	500	•	· · · · · · · · · · · · · · · · · · ·	•	<u></u>				
	1182								
	1682								
1/4	2163						•		
-	2562		·	· . ·					
	3040	•		•					
1/4	3265	•	••••••••••••••••••••••••••••••••••••••						
1/4	3416	•	• • •				•		
1/4	3900	•		· · ·			•		
		•		•			•		
)		•					
		•			<u></u>		•	<u> </u>	
				•		<u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>			
		• •	<u></u>	•	<u></u>				
			· · ·				•		
		•	1 19	Drillin	g Contra	ctor <u>Ca</u>	tus Dri	111ing Com	pany
		•	••	• . '	,	By X	()	1000	DIED
						K	en Hedri	ick Superinte	ndent
becri	bed and i	sworn to	before me this	8thda	y of		July		19 <u>75</u>
		•		:			- 2		
Comm	jasion B	xpirosi		;	Y		ry Publi		
5	- 1- 70	6			Lea	C	ounty,	New Me	exico