STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

30. 07 6071E0 SCCEIVED	T				
DISTRIBUTION					
SANTA PE	1				
FILE					
U.3.0.5.					
LAND OFFICE					
OPPRATOR					

OIL CONSERVATION DIVISION P. O. BOX 2088

Form	C-1	03	٠
Revis	ed	10-	1-

3	AHTA FE] SAN	TA FE. NEV	V MEXICO 87501		Revised 10-1	
ļ	'ILE		4	•		[5a. Indicate Type of Lease	
)	J.S.G.S.	+	4		•		State Fee X	
	PERATOR					ł	5. State Oll & Gas Lease No.	
<u></u>			, ·					
		SUNDR	RY NOTICES AND I	REPORTS ON	WELLS			
	09 CINT BEU TOH 00} 3CU	"APPLICAT	OPOSALS TO PRILL OF TO	DEEPEN ON PLUG	TA . MIFFFELT BESTSUAL	. }		
1.							7. Unit Agreement Name	
OIL WE	il X Wel	L	OTHER-		•			
2. Name	oi Operator						8. Farm or Lease Name	
	Marathon Oi	1 Comp	anv				Walter Lynch	
J. Addr	ess of Operator	-	*				9. Well No.	
		09 Ho	bbs, New Mexico	o 88240			6	
4. Loca	tion of Well					İ	10. Field and Pool, or Wildcat	
Uni	IT LETTER F		2310 PEET PROM 1	North	LINE AND 1980	EET PROM	Wantz granite Wash.	
			•			Ì	.[[]	
THE	West .	.1HC, SECTIO	0» Tov	VNSHIP 22	SRANGE_37E	нмрм.	12 14 14 14 14 14 14 14 14 15 12 12 12 12 12 12 12 12 12 12 12 12 12	
kerre	mmm	m	<i></i>		Do bor on		TKIHAKKIT 'EKKIK	
			/////		DF, RT, GR, etc.)		12. County	
77777		777777		4'; GR 335			Lea	
•••		Check A	Appropriate Box 7	To Indicate N	Nature of Notice, Repor	t or Othe	er Data	
-	NOTIC	E OF IN	NTENTION TO:		SUBSE	EQUENT	REPORT OF:	
	-	7		_		~		
PERFOR	M REMEDIAL WORK M	}	PLUG A	MODHAGA DH	REMEDIAL WORK	님	ALTERING CASING	
	APILY ABAHDOH	₹			COMMENCE DRILLING OPHS.	H	PLUG AND ABANDONMENT	
PULL DI	ALTER CABING	J	CHANGE	PLANS	CASING TEST AND CEMENT JOB			
			•	Г	otHER <u>pipe brader</u> to the surf		onnections	
OTXE	·*			L	to the surf	.ace.	· .	
		mpleted Op	perations (Clearly state	all pertinent det	ails, and give pertinent dates,	including e	stimated date of starting any propo-	
wor)	t) SEE RULE 1103.	•						
			" •				•	
	 Dug out 	well c	ellar to expos	se casing b	radenhead outlets.		•	
	2. Install	l" pip	ing from 2" va	lve on eac	h bradenhead outlet	toa	point above	
	ground	level.	Install 1" va	lye on upp	er end of piping.		•	
	3. Conduct	. 1 1 1		•				
	3. Conduct	ed brad	lenhead pressur	e survey.				
	4. Piping a	erranco	mont ones see					
	4 0	round 1	evel inspects	greated or I	ower valve and clos	ed pos:	ition of valve	
	David Ca	atanach	la inspecte	d and appr	oved by NMOCD Deput	y our o	Gas Inspector,	
			•		•			
					Bra	denhead	-	
		Braden	head Size			Locati		
		9	5/8"	•	East Side of well	head (under flowline)	
						.,	,	
		•						
18. 1 her	oby certify that the ir	dormation .	above is true and compl	lete to the best o	f my knowledge and belief.			
	ml. 1 0		/				+	
SIGNED.	While Lie	eenois	of the same of the	TITLEE1	ngineering Technici	an	DATE 5-17-83	
7		V						
		. 11	112 1		IL & GAS INSPE	CTOR	MAV an ana-	
A P P R OY E D		ever (alanach	TITLE	NIP OF CALITY THAT I		DATE WAY 23 1983	

MAY 20 1983