

INCLINATION REPORT

OPERATOR Dalport Oil Corp. ADDRESS 1134 The 0 Bldg, Corpus Christi, Texas
 LEASE NAME A.L. Christmas #3 WELL NO. 3 FIELD _____
 LOCATION Section 25, T-22S, R-36E, Lea County, New Mexico

DEPTH	ANGLE INCLINATION DEGREES	DISPLACEMENT	DISPLACEMENT ACCUMULATED
498	1/4	2.1912	2.1912
971	1/2	4.1151	6.3063
1386	3/4	5.4365	11.7428
1869	3/4	6.3273	18.0701
2366	1	8.6975	26.7676
2833	1	8.1725	34.9401
3204	1	6.4925	41.4326
3345	1	2.4675	43.9001

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

CACTUS DRILLING COMPANY

Garlin Taylor
 TITLE Garlin Taylor, Admn. Asst.

AFFIDAVIT:

Before me, the undersigned authority, appeared Garlin Taylor known to me to be the person whose name is subscribed herebelow, who, on making deposition, under oath states that he is acting for and in behalf of the operator of the well identified above, and that to the best of his knowledge and belief such well was not intentionally deviated from the true vertical whatsoever.

Garlin Taylor
 AFFIANT'S SIGNATURE

Sworn and subscribed to in my presence on this the 22nd day of August, 1977

MY COMMISSION EXPIRES MARCH 1, 1980

James L. Majors
 Notary Public in and for the County
 of Lea, State of New Mexico

SEAL

RECEIVED

FEB 21 1978

INVESTIGATION COMM.
HONOLULU, H. I.