

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.  
LEASE DESIGNATION AND SERIAL NO.

NM-18634-A

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR Amoco Production Company		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR P. O. Drawer "A", Levelland, Texas 79336		8. FARM OR LEASE NAME Federal "H"	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL & 660' FWL Sec. 26 (Unit L, NW/4, SW/4)		9. WELL NO. 1	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3660.1 GL	
		10. FIELD AND POOL, OR WILDCAT Wildcat - Morrow	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 26-23-33	
		12. COUNTY OR PARISH Lea	
		13. STATE NM	

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) Cement <input checked="" type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

On 6-24-78 McVay Drilling Co. (Rig #10) spudded a 20" hole at 4:00 p.m. Drilled to a TD of 802' and set 16" 75# & 65# H-40 ST&C casing at 802'. Cemented with 952 sacks of Class C. Plugged down 1:30 a.m. 6-26-78. Cement did not circulate. Ran temp survey and found top of cement at 105 feet from the surface. Ran 1" tubing and cemented with 100 sacks Class C. Circulated 10 sacks to surface. Waited on cement 18½ hours. Tested w/1000# for 30 min. OK. Reduced hole to 14 3/4" and resumed drilling.

18. I hereby certify that the foregoing is true and correct

SIGNED Ray W. CoxTITLE Administrative SupervisorDATE 8-15-78

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

0+4 - USGS - H  
1 - Div.  
1 - Susp.  
1 - RC

1 - Southland Roy

\*See Instructions on Reverse Side

DATE ACCEPTED FOR RECORD AUG 17 1978 U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO
--