

Anadarko Petroleum Corp
NMOCD C-103 - Repair hole in casing
Langley Griffin #1

Page 2

8. TIH w/csg scab liner & set top @ 4925' & bottom @ 5070'
9. TIH w/production string and put Strawn on pump. Started testing.
10. Rig down 5-29-98. WOO.
Rig back up 6-15-98
Finished 6-25-98.

3
2