

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Summit Energy, Inc.		8. Farm or Lease Name Amanda Sims
3. Address of Operator 112 North First St., Artesia, New Mexico 88210		9. Well No. 2
4. Location of Well UNIT LETTER <u>I</u> <u>990</u> FEET FROM THE <u>East</u> LINE AND <u>2310</u> FEET FROM THE <u>South</u> LINE, SECTION <u>25</u> TOWNSHIP <u>22 S</u> RANGE <u>37 East</u> NMPM.		10. Field and Pool, or Wildcat Drinkard Oil
15. Elevation (Show whether DF, RT, GR, etc.) 3308.0 GR		12. County Lea

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Test on Granite Wash</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 5-15-80, perforated Granite Wash 7302 - 7451'. Total 18 holes. Treated with 4000 gals. acid and ball sealers. Swabbed back load water, very slight trace of oil. Ran wireline Bridge Plug to 7294'. Tested Bridge Plug to 3000 psi. for 1 hour. Tested o.k..

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Paul Sexton</u>	TITLE <u>Engineer</u>	DATE <u>5-27-80</u>
Orig. Signed by Jerry Sexton Dist. 1, Supg.		
APPROVED BY _____	TITLE _____	DATE <u>MAY 29 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		