

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-14124
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM 18306
2. NAME OF OPERATOR Monsanto Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 1330 Midland NBT, Midland, Texas		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 660' FEL of Section 20 U.S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO		8. FARM OR LEASE NAME Back Basin Unit
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, CR, etc.) 3496 GR		10. FIELD AND POOL, OR WILDCAT Antelope Ridge (Atoka)
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 20, T-23S, R-34E
		12. COUNTY OR PARISH Lea
		13. STATE N. M.

RECEIVED
FEB 20 1981

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Set 5" liner

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drill 7-7/8" hole to 14,150'.
Run 54 jts of 5" 23.3# C-75; Liner length 2182.23'. Set liner btm @ 14,150 & top @ 11,967, circ out gas.
Cement w/250 sxs "H", .8% Halad 22, 44% CFR-2 3#/5k KCL pumped @ 15.6 ppg, had 40 bbls sand spacer ahead of cmt & 10 bbls behind cmt, displ w/230 bbls w/invent mud, plug down 5 A.M.
1/15/81

18. I hereby certify that the foregoing is true and correct

SIGNED

ACCEPTED FOR RECORD
PETER W. CHESTER

TITLE Regional Prod. Mgr.

DATE 2/18/81

(This space for Federal or State acceptance)

APPROVED BY

CONDITIONS OF APPROVAL

FEB 25 1981

TITLE

DATE

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 18306

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Back Basin Unit

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Bell Lake (Morrow)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 20, T-23S, R-34E

12. COUNTY OR PARISH 13. STATE

Lea

N. M.

1. OIL ☐ GAS ☒ OTHER ☐

2. NAME OF OPERATOR

Monsanto Company

3. ADDRESS OF OPERATOR

1330 Midland NBT, Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any applicable regulations. See also space 17 below.)
At surface

1980' FSL & 660' FEL of Section 20

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3496 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Set 5" liner

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drill 7-7/8" hole to 14,150'.

Run 54 jts of 5" 23.3# C-75; Liner length 2182.23'. Set liner btm @ 14,150 & top @ 11,967, circ out gas.

Cement w/250 sxs "H", .8% Halad 22, 44% CFR-2 3#/5k KCL pumped @ 15.6 ppg, had 40 bbls sand spacer ahead of cmt & 10 bbls behind cmt, displ w/230 bbls w/invent mud, plug down 5 A.M. 1/15/81

RECEIVED

FEB 23 1981

U.S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

ACCEPTED FOR RECORD

FEB 20 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Regional Prod. Mgr.

DATE 2/18/81

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: