....

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

_ 1	-MV	19	6	2	0	

LEASE

9. WELL NO.

 TAL		עיי	4	<u> </u>					
IF II	NDL	l N	Δ1 Ι	OT	TEE	ΛÞ	TOID	E N	1 A B

SUNDRY NOTICES AND REPORTS ON WELL	SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
------------------------------------	--------	---------	-----	---------	----	--------------

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)

1.	oil gas well other
	NAME OF OPERATOR
	THE SUPERIOR OIL COMPANY
	ADDRESS OF OPERATOR
	P.O. Box 4500, The Woodlands, TX77380
4.	LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
	AT SURFACE: 660' FSL & 1980' FWL of Sec.1]
	AT TOP PROD. INTERVAL:
	AT TOTAL DEPTH: Straight hole

16.	CHECK	APPROPRIATE	BOX	TO	INDICATE	NATURE	OF	NOTICE,
	REPOR1	r, or other i	ATAC					

7. UNII AGREEMENT NAME	200 (200
8. FARM OR LEASE NAME	
Triste Draw	Culf to dob (

10. FIELD OR WILDCAT NAME

Wildcat 11. SEC., T., R., M., OR BLK. AND SURVEY OR

AREA Sec. 11, T23S-R32E

12. COUNTY OR PARISH 13. STATE New Mexico 14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND V/D) 3728' GL.

REQUEST FOR AFFROME	10.	SUBSEQUENT	REPORT OF:	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING			JAN 1 8 1982 thanks of Form 9-3	tiple completion or zone 30.)
MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Drlg. Opera	tions	Csg. Se	U.S. GEOLOGIA	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 12-28-81 (12,650' MD) 9.0# MW

	Drilling ahead.
12-29-81	Circulated for logs.
	POH. Logged well
12-31-81	Circ. & Conditioned hole for 7-5/8" csg.
1-01-82	Generator failed. WO mechanic 9-1/2 hrs.
1-02-82	Generator repaired.
1-03-82	Ran 293 jts. 7-5/8" csg. to 12,650.
1-04-82	Cemented 7-5/8" csg. w/ll50 sks. Class H,
	displaced w/550 bbls brine. N.U. BOP's & tested.

1-05-82 RU Manifold & Tested. 1-07-82 Tested csg. to 2400 psi-OK.

1-08-82- Drilling ahead (13,400' MD)

1-11-82 9.9 # MW. Subsurface Safety Valve: Manu. and Type __ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

TITLE Reg. Group MgrDATE January 12, 1982 SIGNED ACCEPTED APPROVED BY CONDITIONS (This space for Federal or State office use) TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 2 0 1982

U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO

*See Instructions on Reverse Side