

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well ☐ gas well ☐ other

2. NAME OF OPERATOR

Beach Exploration, Inc.

3. ADDRESS OF OPERATOR

800 N. Marienfeld, Suite 200 MidlandTx

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) show final completion

5. LEASE

DANCIGER NM-39160

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

DANCIGER

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Jalmat-Yates Seven Rivers

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 1, T23S, R35E

12. COUNTY OR PARISH

Lea

13. STATE

NM

14. API NO.

3002527989

15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

First report since 12-10-83.

**Notified of first prod by letter 2-14-83

U.S.G.S. Roswell, New Mexico

1-26-83 Moved 2 (210) bbl tank from our Livermore #1 lease and set.

2-9-83 Moved pump jack in, set water tank and heater treater. Started to connect tank battery.

2-11-83 Pumped 30 BW down casing. Pulled tbg re-ran tbg with 1 joint mud anchor 3' perf nipple. Seating nipple and 117 joints of 2 3/8" tbg. Seating nipple at 3706'. Ran 2" x 1 1/4" x 16' HF 3-2 pump from Livermore #3 then 108 - 5/8" rods and 44 3/4 inch rods. Spaced out and hung on. Hooked up flow line 1 p.m. MST, FINAL REPORT. W/O Phillips Gas Company.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

Linda Hosten

TITLE

Agent

DATE

2/14/82

APPROVED BY
CONDITIONS OF APPROVAL IF ANY:

(ORIG. SGD.) DAVID R. GLASS

DATE

FEB 16 1983

MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

RECEIVED

FEB 16 1983